

Oil Field Environmental Incident Summary

Incident: 20140811091454 **Date/Time of Notice:** 08/11/2014 09:14

Responsible Party: MUREX PETROLEUM CORPORATION

Well Operator: MUREX PETROLEUM CORPORATION

Well Name: DEANNA MARIE 34-27H

Field Name: FORTUNA

Well File #: 25713

Date Incident: 8/9/2014

Time Incident: 12:00

Facility ID Number:

County: DIVIDE

Twp: 162

Rng: 101

Sec: 34

Qtr: SE SW

Location Description:

Submitted By: William Jansky

Received By:

Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1.5 Mile

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	4.5	Barrels	4.5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/3/2016

Clean Up Concluded: 8/2/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Motor and fitting re-tightened.

Wastes Disposal Location: Recovered saltwater water was taken to the Legaard SWD

Agencies Involved:

Updates

Date: 8/13/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.